General Environmental Incident Summary

Incident: 2192 Date/Time Notice: 2/7/2014 0840 DEM Incident No:

Responsible Party: 5th Bomb Wing

Date Incident: 2/6/2014 Time Incident: 1820 Duration:

County: Ward Twp: 157 Rng: 83 Sec: 13 Qtr: SW SE SW

Lat: 48.41530 Long: -101.33370 Method: Interpolation from map

Location Description: Corner of Peacekeeper Place and Bomber Boulevard on Minot Air Force

Base 13 miles north of Minot.

Submitted By: Danny Kluck Affiliation:

Address: 5 CES/CEIE

445 Peacekeeper Place

City: Minot AFB State: ND Zip: 58705

Received By:

Contact Person: Danny Kluck

201 Summit Drive Minot AFB, ND 58705

Distance Nearest Occupied Building: 500 Feet

Type of Incident: Tank Overflow

Description of Released Contaminant: Diesel Fuel

Volume Spilled: 40.00 gallons Ag Related: No EPA Extremely Hazardous Substance: No Reported to NRC: Yes

Cause of Incident:

Fuel contractor was filling above ground storage tank no. 4013 at the military service station and did not hear alarm indicating tank was full and overfilled the tank.

Risk Evaluation:

None.

of Fatalities: 0 # of Injuries: 0 Affected Medium: 01 - air

Potential Environmental Impacts:

Fuel did not reach water. The ground underneath the snow was frozen rock hard preventing the fuel from seeping into the ground.

Action Taken or Planned:

Snow was cleared from around fuel tank concrete pad and absorbent booms were deployed around fuel tank concrete pad perimeter. Absorbent booms were also placed under the fuel tank to absorb fuel on concrete pad. An inspection of the site showed that fuel did run off of the concrete pad into the snow and there is contaminated snow. The contaminated snow on and around the fuel tank concrete pad will be removed to Bldg 418 were it will be allowed to melt and then will be processed through an oil water separator.

Wastes Disposal Location: Contaminated booms were containerized in plastic barrels for disposal

Friday, January 27, 2017 Page 1 of 2

via the base HAZMART. Contaminated snow will be processed through an oil water separator and fuel will be reclaimed.

Agencies Involved:

Updates

Date: 2/10/2014 Status: Reviewed - No Action Required Author: Roberts, Kris

Updated Volume:

Notes:

Based on incident description and response actions in the report, no followup is necessary. Air Force personnel performed the containment and cleanup.